

Noyack

High Water Mark Field Form

(one form per HWM)

SUF-432
Quick Lookup #

DATE: 11/5/12 STORM: Sandy PARTY: ACS / BJM / TCM

SITE INFORMATION

SITE NAME: HWM-NY-SUF-432 LATITUDE (DD to 6 places): 40.9937
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: Noyack Creek LONGITUDE (DD to 6 places): -72.3629

STATE: NY COUNTY: Suffolk Landowner notified (circle one): Yes No

HWM INFORMATION

HWM identified with: colored flagging, marker, stake, disc, spray paint, other _____

Type of mark: debris line, mud line, seed line, wash line, other _____

Mark location (circle one): Inside Outside Approx. height above ground (ft): 2.4

Quality of mark (circle one): Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION


HWM Description: seed line on tree by fence along N side of Cedar lane, in front #79
South 25.5' from centerline of 51' West
from end of fence

HWM Elevation: 6.507

RM Description: Bolt on top lip of Fire Hydrant Facing east of Cedar point bar and Clam Island.

RM #: 1 RM Elevation: 8.302

Other Notes:



→ Clam Is.

PHOTOGRAPH INFORMATION

Pictures Taken: Yes No Camera Owner: ACS, ADL

Digital Photo Filenames: HWM-NY-SUF-432-(01 to 08)-jpg


Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: _____ STORM: _____ PARTY: _____



Additional Notes:

Check HWM on fence & tree
note: secondary mark, incidentally labeled
on fence