(Greenwich)

High Water Mark Field Form

(one form per HWM)

FAI-816
Quick Lookup #

DATE: 11/06/12 STORM: Sandy PARTY: RRB, MLN

SITE INFORMATION

SITE NAME: HWM-CT-FAI-816 **LATITUDE (DD to 6 places):** 41.01664539
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: Grass Island Nature Trail **LONGITUDE (DD to 6 places):** -73.62831916

STATE: CT **COUNTY:** Fairfield **Landowner notified (circle one):** Yes (No)

HWM INFORMATION

HWM identified with: colored flagging, marker, (stake), disc, (spray paint), other _____
Type of mark: (debris line), mud line, seed line, wash line, other _____
Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** 0.00 @ L.S
Quality of mark (circle one): Excellent (+/- 0.05 ft) (Good (+/- 0.10 ft)) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: HWM is debris line @ Entrance to Grass Island Historic Nature Trail. West of Shore Rd.

HWM Elevation: 9.839 ft Above NAVD88

RM Description: NA

RM #: — **RM Elevation:** —

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** MLN

Digital Photo Filenames: HWM-CT-FAI-816 (01-03).jpeg

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: _____ STORM: _____ PARTY: _____

SITE MAP



Additional Notes:

(UTM cord.) = N 14899970.416 E 2018808.995