High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11.5.2012 STORM: SANDY PARTY: DPS / DAL

SITE INFORMATION

SITE NAME: HWM-NJ-ATL-102 **LATITUDE (DD to 6 places):** 39° 23' 50.574"

(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: West shore of Absecon Bay, Northwest side of overpass on Hwy 30. **LONGITUDE (DD to 6 places):** 74° 29' 34.652"

STATE: NJ **COUNTY:** ATL **Landowner notified (circle one):** Yes (No)

HWM INFORMATION

HWM identified with: colored flagging, marker (sharpie), stake, disc, spray paint, other

Type of mark: debris line, mud line, seed line, wash line, other

Mark location (circle one): Inside Outside **Approx. height above ground (ft):** ~3.0'

Quality of mark (circle one): Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: seedline on exterior of abandoned Bayview motel, facing Hwy 30.

HWM Elevation: 7.531 TRM shot 1 = 3.832', TRM shot 2 = 3.838' } $\bar{x}$ = (3.835' TRM)

RM Description: ~1.25' NW of handicap parking place stencil, 1/4" lead hammer in anchor driven into asphalt parking space in front of Abandoned Bayview Motel.

RM #: **RM Elevation:** 4.657, est. off RTN

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** DPS

Digital Photo Filenames: 987-990

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11.05.2012 STORM: SANDY PARTY: DOS / DAL

SITE MAP



Additional Notes:

STATION	B.S.	HT.INST	F.S.	ELEV-ATION	REMARKS
TRM1	5.031	8.866		3.835	
hwm			1.334	7.532	
TP1	4.228	8.885	4.209	4.657	
hwm			1.353	7.532	
TRM1			5.049	3.836	
	1st	2nd	$\bar{x}$		
TRM1	3.697	3.696	3.696	3.835	
hwm				7.531	→ HWM elevation

STATION	B.S.	HT.INST	F.S.	ELEV-ATION	REMARKS

Remarks 11.5.2012, HWM-NJ-ATL-102
shot to HWM waterline on ~~the~~ ext. of abandoned Bayview Motel, facing HW 30, ~~at~~ orgin elv. set by RTN.