High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11.5.2012 STORM: SANDY PARTY: DPS, DAL

SITE INFORMATION

SITE NAME: HWM-NJ-ATL-106 **LATITUDE (DD to 6 places):** 39 22' 39.588"

(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: North side Absecon Inlet. **LONGITUDE (DD to 6 places):** 74° 24' 24.456

STATE: NJ **COUNTY:** ATLANTIC **Landowner notified (circle one):** Yes (No)

HWM INFORMATION

HWM identified with: colored flagging, marker, stake, disc, spray paint, other None, shot on site w/ RTK.

Type of mark: debris line, (mud line), seed line, wash line, other on exterior foundation wall of home,

Mark location (circle one): Inside Outside **Approx. height above ground (ft):** 1.1' abv. driveway

Quality of mark (circle one): Excellent (+/- 0.05 ft) (Good (+/- 0.10 ft)) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: silt line on plastered foundation wall of house @ 51 Ocean Dr. S. . Directly across from junction w/ Sunset Ct.

HWM Elevation: 7.790'

RM Description: Temp RM shot 1 = 6.416' } x̄ 6.407'
shot 2 = 6.398'

RM #: _____ **RM Elevation:** _____

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** DPS

Digital Photo Filenames: 1005 - 1008'

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11.5.2012 STORM: SANDY PARTY: DPS. DAL

SITE MAP



Additional Notes:

_____

_____

_____

_____

STATION	B.S.	HT.INST	F.S.	ELEV-ATION	REMARKS
TRM1	4.285	10.692		6.407	
hwm			2.903	7.789	
TP1	3.957	10.673	3.976	6.716	
hwm			2.882	7.791	
TRM1			4.266	6.407	
	1st	2nd	$\bar{x}$		
TRM1	1.382	1.384	1.383	6.407	
hwm				7.790	→ hwm elevation

STATION	B.S.	HT.INST	F.S.	ELEV-ATION	REMARKS

Remarks HWM-NJ-ATL-106
11.5.2012; visual levels orgin derived from RTN temp. BM.