High Water Mark Field Form

(one form per HWM)

Quick Lookup # _____

DATE: 11/2/12 STORM: Sandy PARTY: DAL/DPS

SITE INFORMATION

SITE NAME: HWM-NJ-MON-117 **LATITUDE (DD to 6 places):** 40° 26' 53.477"

(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: P.S. Marine Services Laurel Rd **LONGITUDE (DD to 6 places):** 74° 8' 31.998"

STATE: NJ **COUNTY:** Monmo-Th **Landowner notified (circle one):** (Yes) No

HWM INFORMATION

HWM identified with: colored flagging, (marker), stake, disc, spray paint, other _____

Type of mark: debris line, mud line, (seed line), wash line, other _____

Mark location (circle one): Inside Outside **Approx. height above ground (ft):** 0.9

Quality of mark (circle one): Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) (Fair (+/- 0.25 ft)) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: seed line on large metal storage building

HWM Elevation: 5.14" shot 1 = 5.124' shot 2 = 5.156' } $\bar{x}$ = 5.14"

RM Description: _____

RM #: _____ **RM Elevation:** _____

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** DPS

Digital Photo Filenames: 872-876

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/2/12 STORM: Sandy PARTY: DAL/DPS

SITE MAP



Additional Notes: