High Water Mark Field Form

(one form per HWM)

Quick Lookup # _____

DATE: 11/3/2012 STORM: Sandy PARTY: CAS / KAC

SITE INFORMATION

SITE NAME: HWM-NJ-MON-202 **LATITUDE (DD to 6 places):** 40.40464
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: 109 Waterwitch Rd **LONGITUDE (DD to 6 places):** 73.99415

STATE: NJ **COUNTY:** Monmouth **Landowner notified (circle one):** (Yes) No

HWM INFORMATION

HWM identified with: colored flagging, (marker), stake, disc, spray paint, other _____
Type of mark: debris line, (mud line), ~~seed line~~, wash line, other _____
Mark location (circle one): (Inside) Outside **Approx. height above ground (ft):** 4.8 ft
Quality of mark (circle one): Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Mud line inside store on right wall upon entrance to store. Store front is approx. 15' from south edge of road. HWM marked nail installed on inside door frame on right. (In the Garden Shop)

HWM Elevation: 10.984 ft (10.980 / 10.989)

RM Description: BM1 located in parking lot of Sand Witch Shop on Shore Dr. approx. 15' from stop sign.

RM #: 1 **RM Elevation:** 6.727 (6.617 / 6.672) 40.40446N 73.99399W

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** CAS

Digital Photo Filenames: _____ _____

_____ _____

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup # _____

DATE: _____ STORM: _____ PARTY: _____

SITE MAP



Additional Notes:

_____

_____

_____

_____

STATION	B.S.	HT.INST	F.S.	ELEV-ATION	REMARKS
BM1	2.646	9.318		6.672	
HWM202			-1.662	10.980	4.8 ft above ground
TP1	2.630	9.314	2.634	6.684	
HWM202			-1.675	10.989	
BM1			2.644	6.670	

STATION	B.S.	HT.INST	F.S.	ELEV-ATION	REMARKS

Remarks

Waterwiten Ave.

HWM- NJ-NOV-202