High Water Mark Field Form

(one form per HWM)

Quick Lookup # _____

DATE: 11/3/2012 STORM: Sandy PARTY: CAS/KAC

SITE INFORMATION

SITE NAME: HWM-NJ-MON-207 **LATITUDE (DD to 6 places):** 40.3626
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: Century 21 Office Ocean Ave **LONGITUDE (DD to 6 places):** 73.97424

STATE: NJ **COUNTY:** Monmouth **Landowner notified (circle one):** Yes (No)

HWM INFORMATION

HWM identified with: colored flagging, marker, stake, disc, spray paint, other Sharpie
Type of mark: debris line, (mud line), seed line, wash line, other _____
Mark location (circle one): (Inside) Outside **Approx. height above ground (ft):** 4.7
Quality of mark (circle one): Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Mud line along right interior wall. Marked in Sharpie approx. 12' from window. Building approximately 6' from road (West side of road)

HWM Elevation: 9.962 9.963 > 9.962 ft

RM Description: Survey Marker in curb on East side of Ocean Avenue at intersection of Ocean Ave + River St. Approx. 15ft north of fire hydrant.

RM #: 3 **RM Elevation:** 3.757 3.691

Other Notes:
Line was wavy due to wave action

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** CAS

Digital Photo Filenames: _____ _____

_____ _____

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: _____ STORM: _____ PARTY: _____

SITE MAP



Additional Notes:

_____

_____

_____

_____

STATION	B.S.	HT.INST	F.S.	ELEV-ATION	REMARKS
BM3	4.217	7.941		3.724	
HWM208			-2.219	10.160	
HWM207			-2.022	9.963	
TP1	3.331	7.937	3.335	4.606	
HWM207			-2.025	9.962	
HWM208			-2.227	10.164	
BM3			4.215	3.722	

HWM-NJ-MON-207 208

STATION	B.S.	HT.INST	F.S.	ELEV-ATION	REMARKS

Remarks

Ocean Ave.