High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/4/2012 STORM: Sandy PARTY: CAS / KAC

SITE INFORMATION

SITE NAME: HWM-NJ-MON-213 **LATITUDE (DD to 6 places):** 40.43239
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: HWY 36 @ Pews CK **LONGITUDE (DD to 6 places):** 74.11310

STATE: NJ **COUNTY:** Monmouth **Landowner notified (circle one):** Yes (No)

HWM INFORMATION

HWM identified with: colored flagging, marker, stake, disc, spray paint, other Sharpie
Type of mark: debris line, (mud line, seed) line, wash line, other
Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** 2.00
Quality of mark (circle one): Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Seed line on concrete marsh overflow retaining wall approximately 125' from north edge of HWY 36 westbound. Mark on north facing retaining wall, furthest from road. Sharpie

HWM Elevation: 13.742 (13.743) > 13.742 − 2.08 = 11.662

RM Description:

RM #: **RM Elevation:**

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** CAS

Digital Photo Filenames:

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: _____ STORM: _____ PARTY: _____

SITE MAP



Additional Notes:

_____