High Water Mark Field Form

(one form per HWM)

Quick Lookup # _____

DATE: 11/4/2012 STORM: Sandy PARTY: CAS / KAC

SITE INFORMATION

SITE NAME: HWM-NJ-Mon-~~316~~ 316 **LATITUDE (DD to 6 places):** 40.33405

(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: 130 Lippincott Road **LONGITUDE (DD to 6 places):** 74.02939

STATE: NJ **COUNTY:** Monmouth **Landowner notified (circle one):** (Yes) No

HWM INFORMATION

HWM identified with: colored flagging, marker, stake, disc, spray paint, other none

Type of mark: debris line, mud line, seed line, wash line, other _____

Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** 3.3 ft

Quality of mark (circle one): Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Seed and mud line on fence at northwest side of residence at 130 Lippincott Rd. Fence is approx. 60' from road edge.

HWM Elevation: 9.696 / 9.675 (> 9.686 ft)

RM Description: Survey marker in pavement ~7' NE of curb in front of 130 Lippincott Rd. 60' N of mailbox and driveway to 130 Lippincott Rd.

RM #: BM2 **RM Elevation:** 5.332 / 5.346 > 5.339

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** _____

Digital Photo Filenames: _____ _____

_____ _____

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: _____ STORM: _____ PARTY: _____

SITE MAP



Additional Notes:

_____

_____

_____

_____

STATION	B.S.	HT.INST	F.S.	ELEV-ATION	REMARKS
BM2	4.999	10.338		5.339	
HWM216			0.642	9.696	
HWM217			0.604	9.734	
TP1	2.849	10.318	2.869	7.469	
HWM217			0.580	9.738	
HWM216			0.643	9.675	
BM2			4.977	5.341	
		216 →	9.686		
		217 →	9.734		
		~~HWM-NT-MON~~			~~316~~ 317

STATION	B.S.	HT.INST	F.S.	ELEV-ATION	REMARKS

Remarks

Lippencott Drive