High Water Mark Field Form

(one form per HWM)

KIN - 003
Quick Lookup #

DATE: 12/20/12 STORM: Sandy PARTY: RRB, MN

SITE INFORMATION

SITE NAME: HWM-NY-KIN-003 **LATITUDE (DD to 6 places):** N 40.644537
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: E. 108th St + Flatlands 4th St. **LONGITUDE (DD to 6 places):** W077.888147

STATE: NY **COUNTY:** Queens **Landowner notified (circle one):** Yes (No)

HWM INFORMATION

HWM identified with: colored flagging, (marker), stake, disc, spray paint, other _____
Type of mark: debris line, mud line, (seed line), wash line, other _____
Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** 4.05 ft above L.S.
Quality of mark (circle one): Excellent (+/- 0.05 ft) (Good (+/- 0.10 ft)) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: is a seed line on Garage door on west side of residence 1152 E. 108st. North west Corner of E. 108th St and Flatlands 4th St.

HWM Elevation: 11.027 ft above NAVD 88

RM Description: Square cut on curb by guard rail across the street east of Residence 1152 E. 108th St.

RM #: 32 **RM Elevation:** 7.161 ft Above NAVD 88

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** MN

Digital Photo Filenames: _____ _____

_____ _____

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: _____ STORM: _____ PARTY: _____

SITE MAP



Additional Notes:

_____

_____

_____

_____