High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/1/12 STORM: Sandy PARTY: ACD/CJH

SITE INFORMATION

SITE NAME: HWM-NY-Kin-904 **LATITUDE (DD to 6 places):** 40.59519
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: Gravesend Bay @ ext of Bay Parkway **LONGITUDE (DD to 6 places):** 74.00007

STATE: NY **COUNTY:** King **Landowner notified (circle one):** (Yes) No

HWM INFORMATION

HWM identified with: colored flagging, marker, stake, disc, spray paint, other Screw in Sheetrock
Type of mark: debris line, mud line, (seed line), wash line, other
Mark location (circle one): (Inside) Outside **Approx. height above ground (ft):** 1.10
Quality of mark (circle one): (Excellent (+/- 0.05 ft)) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Seed line inside Glass entrance for HSBC Bank by ATM's. Set screw @ seed line.

HWM Elevation:

RM Description: Nail set in Parking lot approx 50' from Entrance of HSBC Bank

RM #: 1 **RM Elevation:** 9.1785

LEVELS RAN TO DETERMINE ELEV.

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** CJH

Digital Photo Filenames: HWM-NY-Kin-904-1
HWM-NY-Kin-904-2

Please complete site sketch on reverse

$$\frac{9.142 + 9.215}{2} = 9.1785$$

678 410
6916

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/1/12 STORM: Sandy PARTY: ACD/CJH



Additional Notes:

Ran short set of levels from RM1 to HWM904 on seperate sheet

STATION	B.S.	HT.INST	F.S.	ELEV-ATION	REMARKS
RM1	5.672	14.8505		9.1785	
HWM904			3.383	11.4675	
TP1	0.773	14.9715	0.652	14.1985	
HWM904			3.504	11.4675	
RM1			5.793	9.1785	

HWM-NY-KIN-904 11/1/12 CJH/ACD

STATION	B.S.	HT.INST	F.S.	ELEV-ATION	REMARKS

Remarks