High Water Mark Field Form

(one form per HWM)

Quick Lookup # _____

DATE: 11/2/12 STORM: Sandy PARTY: ACD/CJH

SITE INFORMATION

SITE NAME: HWM-NY-Kin-905 **LATITUDE (DD to 6 places):** 40.58019
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: Gravesend Bay @ Leon Kaiser Playground **LONGITUDE (DD to 6 places):** 73.99792

STATE: NY **COUNTY:** Kings **Landowner notified (circle one):** Yes (No)

HWM INFORMATION

HWM identified with: colored flagging, marker, stake, disc, (spray paint), other Stake
Type of mark: (debris line), mud line, seed line, wash line, other _____
Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** 0.0 on Ground
Quality of mark (circle one): Excellent (+/- 0.05 ft) (Good (+/- 0.10 ft)) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Stake driven in ground at debris line on hill between track and Beach area.

HWM Elevation: 11.457

RM Description: _____

RM #: _____ **RM Elevation:** _____

Other Notes: _____

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** CJH

Digital Photo Filenames: HWM-NY-Kin-905-1
HWM-NY-Kin-905-2

Please complete site sketch on reverse

11.451
11.463
11.457 Avg

High Water Mark Field Form

(one form per HWM)

Quick Lookup # _____

DATE: 11/2/12 STORM: Sandy PARTY: ACD/CJH



Additional Notes:

_____

_____

_____

_____