High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/2/12 STORM: Sandy (2012) PARTY: WDC / MDC

SITE INFORMATION

SITE NAME: HWM-NY-NAS-707 **LATITUDE (DD to 6 places):** 40.583975
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: Pacific and Shore Rd - Long Beach **LONGITUDE (DD to 6 places):** -73.640810

STATE: NY **COUNTY:** Nassau **Landowner notified (circle one):** Yes (No)

Notes unrelated to HWM

HWM INFORMATION

HWM identified with: colored flagging, marker, stake, disc, spray paint, (other) Nail w/ white USGS tag
Type of mark: debris line, mud line, seed line, (wash line), other
Mark location (circle one): Inside Outside **Approx. height above ground (ft):** 1.14
Quality of mark (circle one): Excellent (+/- 0.05 ft) (Good (+/- 0.10 ft)) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Nail with white USGS tag in wood wall on wash line

HWM Elevation: 10.66

RM Description: NA

RM #: - **RM Elevation:** -

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** MDC Knaab

Digital Photo Filenames: HWM-NY-NAS

Please complete site sketch on reverse

Cal (229) 326 1818
Chris (770) [illegible]

[illegible] towards Houseblock
Make right ~~before~~ @ Fire-Rescue
first left

Cars parked outside building

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/2/12 STORM: Sandy (2012) PARTY: WDC / MDC

SITE MAP



Additional Notes:

Additional HWM

Nail w/ white USGS disk in wood next to 72 Pacific Blvd garage door. 1.58 ft above land surface.