High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/2/12 STORM: Sandy (2012) PARTY: WDC / MDC

SITE INFORMATION

SITE NAME: HWM-NY-NAS-709 **LATITUDE (DD to 6 places):** 40.593357
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: Long Beach Ice Arena **LONGITUDE (DD to 6 places):** 73.668923

STATE: NY **COUNTY:** Nassau **Landowner notified (circle one):** Yes No

HWM INFORMATION

HWM identified with: colored flagging, marker, stake, disc, spray paint, other
Type of mark: debris line, mud line, seed line, wash line, other
Mark location (circle one): Inside Outside **Approx. height above ground (ft):** 0.80 above floor
Quality of mark (circle one): Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Mark on top of excellent wash line on wall inside Long Beach Ice Arena

HWM Elevation: 8.7295

RM Description: Concrete anchor set in curb between park gate & Arena Entrance

RM #: 1 **RM Elevation:** 5.840

Other Notes:
Contact: Marlon Lainez 1-516-581-9970

PHOTOGRAPH INFORMATION

Pictures Taken: Yes No **Camera Owner:** MDC

Digital Photo Filenames:

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/2/12 STORM: Sandy PARTY: WDC / MDC

SITE MAP



Additional Notes:

For access contact Marlon Lainez 1-516-581-9970

STATION	B.S.	HT.INST	F.S.	ELEV-ATION	REMARKS
RM1	6.913	12.753		5.840	
HWM709			4.033	8.720	
TP1	4.149	12.775	4.127	8.626	
HWM709			4.036	8.739	
RM1			6.933	5.842	

RM1 concrete Anchor set in curb between Park Gate & Arena Entrance

STATION	B.S.	HT.INST	F.S.	ELEV-ATION	REMARKS

Remarks RM elevations 5.840
5.820
5.859 HWM 709 Avg elev
5.8395 Avg 8.7295



Long Beach Ice Arena