High Water Mark Field Form

(one form per HWM)

Quick Lookup # _____

DATE: 11/2/12 STORM: Sandy (2012) PARTY: MDC/WDC

SITE INFORMATION

SITE NAME: HWM-NY-NAS-712 **LATITUDE (DD to 6 places):** 40.591853

(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: 571 West Fulton/Bay **LONGITUDE (DD to 6 places):** -73.680873

STATE: NY **COUNTY:** Nassau **Landowner notified (circle one):** Yes No

HWM INFORMATION

HWM identified with: colored flagging, marker, stake, disc, spray paint, other _____

Type of mark: debris line, mud line, seed line, wash line, other _____

Mark location (circle one): Inside Outside **Approx. height above ground (ft):** _____

Quality of mark (circle one): Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Marker on white fence on top of good wash line. Mark is on fence behind 571 West Fulton on West Bay.

HWM Elevation: 9.485

RM Description: mark on driveway paverstone @ 571 W. Bay Drive

RM #: 1 **RM Elevation:** 7.484

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: Yes No **Camera Owner:** MDC

Digital Photo Filenames: _____ _____

_____ _____

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/2/12 STORM: Sandy (2012) PARTY: MDC/WDC

SITE MAP



Additional Notes:

Orange arrow painted on road near HWM

STATION	B.S.	HT.INST	F.S.	ELEV-ATION	REMARKS
RM1	4.354	11.838		7.484	
HWM 712			2.348	9.490	
TP1	5.221	11.901	5.158	6.680	
HWM712			2.421	9.480	
RM1			4.420	7.481	

HWM-NY-NAS-712 11/03/12

ACP/CJH

STATION	B.S.	HT.INST	F.S.	ELEV-ATION	REMARKS

Remarks RM Elevations 7.417

7.551

HWM912 = 9.485 7.484 Avg

RM1 - mark on paver stone on drive way @ 571 W Bay Drive