Wantagh

High Water Mark Field Form

(one form per HWM)

NAS-907
Quick Lookup #

DATE: 11/1/2012 12/17/12 STORM: SANDY PARTY: SCF & GTEK L.T. Brooks, L.O. Szabo

SITE INFORMATION

SITE NAME: HWM-NY-NAS-907 LATITUDE (DD to 6 places): 40.64879

(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: 2865 Mandalay Beach Road. LONGITUDE (DD to 6 places): -073.51624

STATE: NY COUNTY: NASSAU Landowner notified (circle one): (Yes) No

HWM INFORMATION

HWM identified with: colored flagging, marker, (stake) (orange), disc, spray paint, other _____

Type of mark: debris line, mud line, (seed line), wash line, other _____

Mark location (circle one): Inside (Outside) Approx. height above ground (ft): 0.91 ft. from top of stake flush w/ ground

Quality of mark (circle one): Excellent (+/- 0.05 ft) (Good (+/- 0.10 ft)) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: high water mark on fence consistent ground house 2865 Mandalay Beach Road.

HWM Elevation: 8.54 [redacted]

RM Description: 30 ft from curb. orange ~~one~~ stake driven into ground by fence. no leaves visible

RM #: ____ RM Elevation: 6.451 + 2.09 ft above stake = 8.541

Other Notes:
Used alternate mark, Accessed 9 satellites in survey.

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No Camera Owner: GTEK

Digital Photo Filenames: HWM-NY-NAS-907-(01-05).jpg
HWM-NY-NAS-907-(06-10)alt.jpg

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/1/2012 STORM: SANDY PARTY: SF & GEK

SITE MAP



Additional Notes:

see 907alt field form for more detail