BELLMORE

High Water Mark Field Form

(one form per HWM)

NAS-908
Quick Lookup #

DATE: 11/01/2012 (12/17/12) STORM: SANDY PARTY: SCF, GEK L.O. Szabo, L.T. Brooks

SITE INFORMATION

SITE NAME: HWM-NY-NAS-908 LATITUDE (DD to 6 places): 40.66016 ~~40.660146~~

(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: 2519 SUNRISE AVE LONGITUDE (DD to 6 places): -73.52917

STATE: NY COUNTY: NASSAU Landowner notified (circle one): (Yes) No

HWM INFORMATION

HWM identified with: colored flagging, marker, (stake), disc, spray paint, other

Type of mark: debris line, mud line, (seed line), wash line, other

Mark location (circle one): Inside (Outside) Approx. height above ground (ft): 2.45 ft Top top of stake to top of HWM

Quality of mark (circle one): (Excellent (+/- 0.05 ft)) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: HWM on side of vinyl fence ON house # 2519 Sunrise Ave

HWM Elevation: 8.56 ~~[illegible] ft~~ orange

RM Description: Stake in ground to bare surface 39 feet from curb. Next to telephone pole #7 in front of 2519 SUNRISE AVE

RM #: TBM RM Elevation: 4.894

4.894 TBM
+ 1.215 stake
+ 2.45 HWM above stake
8.56 - HWM elevation

Other Notes:
Accessed 8 satellites

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No Camera Owner: GEK

Digital Photo Filenames: HWM-NY-NAS-908-(01-07).jpg

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/1/2012 STORM: SANDY PARTY: SF & GEK

SITE MAP



Additional Notes: