EAST ROCKAWAY

High Water Mark Field Form

(one form per HWM)

NAS-916
Quick Lookup #

DATE: 11/2/2012 12/18/12 STORM: SANDY PARTY: SCF, GEK L.O. Szabo, L.T. Brooks

SITE INFORMATION

SITE NAME: HWM - NY - NAS - 916 **LATITUDE (DD to 6 places):** 40.64152

(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: apt building door to the right of # 3804 Ocean Ave **LONGITUDE (DD to 6 places):** -073.65965

STATE: NY **COUNTY:** NASSAU **Landowner notified (circle one):** Yes (No)

HWM INFORMATION

HWM identified with: colored flagging, marker, (stake), disc, spray paint, other _____

Type of mark: debris line, mud line, (seed line), wash line, other _____

Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** 1.79 feet from top of stake @ ground level

Quality of mark (circle one): Excellent (+/- 0.05 ft) (Good (+/- 0.10 ft)) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: visible outside apartment building exterior and interior # 3804. door to the right of apt #3804 of Ocean Ave

HWM Elevation: 8.52

6.728
1.79
8.518

RM Description: Stake in ground next to white door on the left of door 35 feet from door stake to corner of curb

RM #: _____ **RM Elevation:** 6.728

Other Notes: GPS accessed 8 satellites

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** SF

Digital Photo Filenames: HWM-NY-NAS-916-(01-08).jpg
HWM-NY-NAS-916-(09-12)alt.jpg

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/2/2012 STORM: SANDY PARTY: SF & GEK

SITE MAP



Survey marker nail inside parking lot

1.78 from nail

secondary

40.64185
073.65965

survey marker in ground, corner of building

Additional Notes: