OCEANSIDE

High Water Mark Field Form

(one form per HWM)

NAS-918
Quick Lookup #

DATE: 11/02/2012 STORM: SANDY PARTY: SCF & GEK

SITE INFORMATION

SITE NAME: HWM - NY - NAS - 918 **LATITUDE (DD to 6 places):** 40.63071
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: 262 WAUKENA AVE in front of house by door and garage **LONGITUDE (DD to 6 places):** -073.63131

STATE: NY **COUNTY:** NASSAU **Landowner notified (circle one):** Yes (No)

HWM INFORMATION

HWM identified with: colored flagging, marker, (stake), disc, spray paint, other _____
Type of mark: debris line, mud line, (seed line), wash line, other _____
Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** 1.63 ft from top of stake @ groundlevel
Quality of mark (circle one): (Excellent (+/- 0.05 ft)) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: SEED LINE IN FRONT OF 262 WAUKENA IN front of house by door and garage.

HWM Elevation: Prim 9.40 Sec. 9.71

7.768 + 1.63 = 9.398
8.762 + 0.95 = 9.712

RM Description: 36 ft from stake to corner curb

RM #: _____ **RM Elevation:** Prim. 7.768 Sec. 8.762

Other Notes:
GPS Accessed 8 satellites

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** SF

Digital Photo Filenames: HWM-NY-NAS-918-(01-05).jpg
HWM-NY-NAS-918-(06-10)alt.jpg

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/2/2012 STORM: SANDY PARTY: SF & GEK



Additional Notes:

_____

_____

_____

_____