High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/03/12 STORM: SANDY PARTY: Shawn + Jason

SITE INFORMATION

SITE NAME: HWM-NY-NAS-928 **LATITUDE (DD to 6 places):** 40.87341

(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: On fence at end of Steamboat Landing Rd **LONGITUDE (DD to 6 places):** -073.51664

STATE: NY **COUNTY:** Nassau **Landowner notified (circle one):** Yes No

HWM INFORMATION

HWM identified with: colored flagging, marker, stake, disc, spray paint, other _____

Type of mark: debris line, mud line, seed line, wash line, other _____

Mark location (circle one): Inside Outside **Approx. height above ground (ft):** 1.18 above cement step

Quality of mark (circle one): Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Seed line on wooden fence next to cement step at end of Steamboat Landing Rd

HWM Elevation: 10.01

RM Description: _____

RM #: _____ **RM Elevation:** _____

Other Notes: _____

PHOTOGRAPH INFORMATION

Pictures Taken: Yes No **Camera Owner:** Riley

Digital Photo Filenames: _____ _____

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11-03-12 STORM: SANDY PARTY: Shawn + Jason



Additional Notes: