High Water Mark Field Form

(one form per HWM)

Quick Lookup # _____

DATE: 11-03-12 STORM: Sandy PARTY: Shawn + Jason

SITE INFORMATION

SITE NAME: HWM-NY-NAS-935 **LATITUDE (DD to 6 places):** 40.91084

(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: 6 Shorewood Dr. **LONGITUDE (DD to 6 places):** -073.55811

STATE: NY **COUNTY:** Nassau **Landowner notified (circle one):** (Yes) No

HWM INFORMATION

HWM identified with: colored flagging, marker, (stake), disc, spray paint, other _____

Type of mark: debris line, mud line, (seed line), wash line, other _____

Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** 1.70 above stake

Quality of mark (circle one): (Excellent (+/- 0.05 ft)) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Seed line along white fence in backyard of 6 Shorewood Dr

HWM Elevation: 11.06

RM Description: _____

RM #: _____ **RM Elevation:** _____

Other Notes: _____

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** R. Ng

Digital Photo Filenames: _____ _____

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11-03-12 STORM: Sandy PARTY: Shawn & Jason

SITE MAP



Additional Notes:

Seed line along white back fence.