Glen Cove

High Water Mark Field Form

(one form per HWM)

NAS-939
Quick Lookup #

DATE: 11-01-12 STORM: SANDY PARTY: SC F + JSF

SITE INFORMATION

SITE NAME: HWM-NY-NAS-939 **LATITUDE (DD to 6 places):** 40.89939
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: 19 Eastland Dr, Glen Cove **LONGITUDE (DD to 6 places):** -073.62746

STATE: NY **COUNTY:** Nassau **Landowner notified (circle one):** Yes (No)

HWM INFORMATION

HWM identified with: (colored flagging), (marker), stake, disc, spray paint, other _____
Type of mark: debris line, mud line, (seed line), wash line, other _____
Mark location (circle one): Inside Outside **Approx. height above ground (ft):** .79 from ground to middle of nail
Quality of mark (circle one): Excellent (+/- 0.05 ft) (Good (+/- 0.10 ft)) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: HWM on small tree in between driveway & garage. Ran a line from seed line on garage to small tree

HWM Elevation: _____

RM Description: _____

RM #: _____ **RM Elevation:** _____

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** Riley

Digital Photo Filenames: HWM-NY-NAS-939-(01-08).jpg
~~HWM-NY-NAS-939-(01-08)alt.jpg~~

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11-04-12 STORM: SANDY PARTY: Shaun & Jason.

SITE MAP



Additional Notes:

Hwm on small tree. Marker placed on tree/orange flag

Hwm on garage signified by permanent marker.