# High Water Mark Field Form

(one form per HWM)

NEW -001
Quick Lookup #

DATE: 12/28/2012 STORM: Sandy PARTY: WDC AES

## *SITE INFORMATION*

**SITE NAME:** HWM-NY-NEW-001 **LATITUDE (DD to 6 places):** 40.7776
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

**SITE DESCRIPTION:** Carl Schurz Park **LONGITUDE (DD to 6 places):** -73.9425

**STATE:** NY **COUNTY:** New York **Landowner notified (circle one):** Yes (No)

## *HWM INFORMATION*

**HWM identified with:** colored flagging, marker, stake, disc, spray paint, (other) _____
**Type of mark:** (debris line), mud line, seed line, wash line, other _____
**Mark location (circle one):** (Inside) (Outside) **Approx. height above ground (ft):** 2.40
**Quality of mark (circle one):** Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) (Poor (>0.25 ft)

## *ELEVATION INFORMATION*

**HWM Description:** Debris line of vegetation in grass North side of fenced area See Sketch

**HWM Elevation:** 10.432

**RM Description:** Wooden Stake 1.38' below HWM

**RM #:** TBM1 **RM Elevation:** 9.052

**Other Notes:**

## *PHOTOGRAPH INFORMATION*

**Pictures Taken:** (Yes) No **Camera Owner:** AES

**Digital Photo Filenames:** HWM-NY-NEW-001 (-01 to -09) .jpg

Please complete site sketch on reverse

# High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 12/28/2012 STORM: Sandy PARTY: VDC AES




**Additional Notes:**

HWM on Ornamental grass

RM - Temporary wooden stake

HWM = RM Elevation + T-pcup

9.052 + 1.381