High Water Mark Field Form

(one form per HWM)

NEW - 004
Quick Lookup #

DATE: 1/3/2013 STORM: Sandy PARTY: WDC / AES

SITE INFORMATION

SITE NAME: HWM – NY – NEW – 004 **LATITUDE (DD to 6 places):** 40.76312
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: Pier 84 by Intrepid **LONGITUDE (DD to 6 places):** -74.00047

STATE: NY **COUNTY:** New York **Landowner notified (circle one):** Yes (No)

HWM INFORMATION

HWM identified with: colored flagging, (marker), stake, disc, spray paint, other _____
Type of mark: debris line, mud line, (seed line), wash line, other _____
Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** 2.60
Quality of mark (circle one): (Excellent (+/- 0.05 ft)) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Seed line on Pier 84 Supply Company East Side

HWM Elevation: 10.346

RM Description: Square cut on Paving Block approximately 30' East of HWM

RM #: 1 **RM Elevation:** 7.405

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** AES

Digital Photo Filenames: HWM-NY-NEW-004 (-01 to -12) .JPG

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 1/3/2012 STORM: Sandy PARTY: WDC AES

SITE MAP



Additional Notes:

HWM is seedline on back side of Pier 84 Company building