(Inwood)

High Water Mark Field Form

(one form per HWM)

NEW-802
Quick Lookup #

DATE: 11/3/12 STORM: Sandy PARTY: RRB, MLN

SITE INFORMATION

SITE NAME: HWM-NY-NEW-802 **LATITUDE (DD to 6 places):** 40° 52' 37.2" N
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: Northern New York county (Inwood Hill Park) near Hudson River **LONGITUDE (DD to 6 places):** 73° 55' 33.7" W

STATE: NY **COUNTY:** New York **Landowner notified (circle one):** Yes (No)

HWM INFORMATION

HWM identified with: colored flagging, marker, (stake), disc, (spray paint), other
Type of mark: (debris line), mud line, seed line, wash line, other
Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** 0.00 @ L.S.
Quality of mark (circle one): Excellent (+/- 0.05 ft) (Good (+/- 0.10 ft)) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: HWM is a debris line on east side of cove east of Rail road tracks and south of sensor. ~ 20 ft east of sandy Beach ~ 15 ft up the hill.

HWM Elevation: 9.532 ft above NAVD 88

RM Description: Anchor bolt in limestone Block south of sensor.

RM #: 1 **RM Elevation:** 8.161 ft above NAVD 88

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** MLN

Digital Photo Filenames: HWM-NY-NEW-802 (01-02)

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: _____ STORM: _____ PARTY: _____

SITE MAP



Additional Notes:

HWM-NY-NEW-802A; is a seed line on concrete wall ~ 100 ft South of sensor next to Rail road tracks. 1.06 ft above land surface. Marker line Drawn on seed line. Rating Good - Fair. Lat = 40° 52' 38.4" N Long = 73° 55" 35.6" W HWM Elevation = 9.339 ft above NAVD88