High Water Mark Field Form

(one form per HWM)

Quick Lookup # _____

DATE: 11-2-12 STORM: Sandy PARTY: AEK / JOS

SITE INFORMATION

SITE NAME: HWM-NY-QUE-508 **LATITUDE (DD to 6 places):** 40.65267
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: Private Res. **LONGITUDE (DD to 6 places):** 73.84222

STATE: NY **COUNTY:** Queens **Landowner notified (circle one):** Yes No

HWM INFORMATION

HWM identified with: colored flagging, marker, stake, disc, spray paint, other None
Type of mark: debris line, mud line, seed line, wash line, other –
Mark location (circle one): Inside Outside **Approx. height above ground (ft):** 2.70' Abv. Gnd
Quality of mark (circle one): Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Good seed line on fence

HWM Elevation: 10.79

RM Description: _____

RM #: N/A **RM Elevation:** _____

Other Notes: _____

PHOTOGRAPH INFORMATION

Pictures Taken: Yes No **Camera Owner:** AEK

Digital Photo Filenames: HWM-NY-QUE-508

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11-2-12 STORM: Sandy PARTY: AEK/JOS

SITE MAP



Additional Notes: