Fort Totten

High Water Mark Field Form

(one form per HWM)

Quick Lookup # _____

DATE: 11/5/12 STORM: Sandy PARTY: ADL/DAS/ESR

SITE INFORMATION

SITE NAME: HWM-NY-QUE-521 **LATITUDE (DD to 6 places):** 40.79350774
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: Fort Totten **LONGITUDE (DD to 6 places):** 73.78057058

STATE: NY **COUNTY:** Queens **Landowner notified (circle one):** (Yes) No

HWM INFORMATION

HWM identified with: (colored flagging), marker, stake, disc, spray paint, other _____
Type of mark: (debris line), mud line, seed line, wash line, other _____
Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** @ ground level
Quality of mark (circle one): Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) (Poor) (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Poor debris line in grass 50 ft. east of Police Dept. pier, 100 ft. west of Little Bay Rd. in Fort Totten Park.

HWM Elevation: 10.56 avg. of 2 ground shots

RM Description: TBM, screw in stake in field 100 ft. northeast of Police Dept. pier, 50 ft. west of Little Bay Rd. in Fort Totten Park.

RM #: GPS HUB1 **RM Elevation:** 12.686

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** ADL

Digital Photo Filenames: HWM-NY-QUE-521-(01-04).jpg

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/5/12 STORM: Sandy PARTY: ADL/DAS/ESR



Additional Notes: