Tottenville Beach, NY

High Water Mark Field Form

(one form per HWM)

RIC-703
Quick Lookup #

DATE: 11/1/12 STORM: Sandy (2012) PARTY: WDC / MDC

SITE INFORMATION

SITE NAME: HWM-NY-RIC-703 **LATITUDE (DD to 6 places):** 40.49965
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: 426 Manhattan St. **LONGITUDE (DD to 6 places):** -74.24120

STATE: NY **COUNTY:** Richmond **Landowner notified (circle one):** (Yes) No

HWM INFORMATION

HWM identified with: colored flagging, (marker), stake, disc, spray paint, other _____
Type of mark: debris line, mud line, (seed line), wash line, other _____
Mark location (circle one): Inside Outside **Approx. height above ground (ft):** 5.54
Quality of mark (circle one): Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) (Fair (+/- 0.25 ft)) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Black mark on ~~white~~ seed line on white fence on Billop Ave. side of 426 Manhattan St.

HWM Elevation: 13.21

RM Description: _____

RM #: _____ **RM Elevation:** _____

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** MDC

Digital Photo Filenames: HWM-NY-RIC-703-a through HWM-NY-RIC-703-03

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/1/12 STORM: Sandy (2012) PARTY: WDC / MDC

SITE MAP



Additional Notes: