High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/6/2012 STORM: SANDY PARTY: DPS / DAL

SITE INFORMATION

SITE NAME: HWM-NY-RIC-720 **LATITUDE (DD to 6 places):** 40°36'55.455"
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: Alice Austen Park **LONGITUDE (DD to 6 places):** 74°3'46.402"

STATE: NY **COUNTY:** RICHMOND **Landowner notified (circle one):** Yes (No)

HWM INFORMATION shot levels w/ RTN.

HWM identified with: colored flagging, marker, (stake), disc, spray paint, other _____
Type of mark: (debris line), mud line, seed line, wash line, other _____
Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** 0
Quality of mark (circle one): Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) (Poor (>0.25 ft))

ELEVATION INFORMATION

HWM Description: orange wooden stake in ground @ top of defined debris line edge @ Alice Austin Park. Elev. of debris line variable due to wave action on this shore that faces NY BAY.

HWM Elevation: 15.314 15.318 15.311

RM Description: _____

RM #: _____ **RM Elevation:** _____

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** DPS

Digital Photo Filenames: HWM NY RIC 720 B, 720B(1), 720B(2), 720B(3). (1048-1051)

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup # _____

DATE: 11/6/2012 STORM: SANDY PARTY: DPS/DAL

SITE MAP



Additional Notes:

_____

_____

_____

_____