West Islip

High Water Mark Field Form

(one form per HWM)

SUF-405
Quick Lookup #

DATE: 11/1/12 STORM: Sandy PARTY: AES / BJM / TLM

SITE INFORMATION

SITE NAME: HWM-NY-SUF-405 **LATITUDE (DD to 6 places):** 40°41'28.4"
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: Oak Neck Ln **LONGITUDE (DD to 6 places):** -73°16'38.0"

STATE: NY **COUNTY:** Suffolk **Landowner notified (circle one):** Yes No

HWM INFORMATION

HWM identified with: colored flagging, marker, stake, disc, spray paint, other _____
Type of mark: debris line, mud line, seed line, wash line, other _____
Mark location (circle one): Inside Outside **Approx. height above ground (ft):** 2.87
Quality of mark (circle one): Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: wash line on whitefence at 36 Oak Neck Ln

HWM Elevation: 5.824 ft above NAVD 88

RM Description: Square cut in curb in front of House 36 on Oak Neck Ln

RM #: 29 **RM Elevation:** 2.906 ft. above NAVD 88

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: Yes No **Camera Owner:** AES

Digital Photo Filenames: HWM-NY-SUF-405-(01-12).jpg

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: _____ STORM: _____ PARTY: _____

SITE MAP



Additional Notes:

Check HWM #1 wash line on silver pole

#2 Transposed HWM to 16" maple tree 20' SE of edge of fence & approx 150' from centerline of Trues Dr. (Sentinel mark)