Riverside

High Water Mark Field Form

(one form per HWM)

SUF-408
Quick Lookup #

DATE: 11-2-12 STORM: Sandy PARTY: BDM/TLM/AES

SITE INFORMATION

SITE NAME: HWM-NY-SUF-408 **LATITUDE (DD to 6 places):** 40°54'54.0"
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: Downtown Riverhead **LONGITUDE (DD to 6 places):** 72°39'42.1"

STATE: NY **COUNTY:** Suffolk **Landowner notified (circle one):** Yes No

HWM INFORMATION

HWM identified with: colored flagging, marker, stake, disc, spray paint, other twisted wire to post for handicap sign alight
Type of mark: debris line, mud line, seed line, wash line, other
Mark location (circle one): Inside Outside **Approx. height above ground (ft):** 0.83 (disk w/ 2 nail)
Quality of mark (circle one): Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: seed line right at door to apt. # 2L6 in parking lot of Fletcher's Barber Shop rt. 24, mark was confirmed by tenant in Apt 2L6

HWM Elevation: 7.80

RM Description: HWM ON RESERVED PARKING POLE (Bm LEVELED FROM HWM)

RM #: ____ **RM Elevation:** ____

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: Yes No **Camera Owner:** AES

Digital Photo Filenames: HWM-NY-SUF-408-(01-09).jpg

Please complete site sketch on reverse

SUF 408

Trimble on TBM

7.400
7.377 > 7.388

12/19/12 KM/TJG

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 10/17/12 STORM: Sandy PARTY: SK/JSF



Additional Notes:

_____

_____

_____

_____