Mastic Beach

High Water Mark Field Form

(one form per HWM)

SUF-415
Quick Lookup #

DATE: 4/2/12 STORM: Sandy PARTY: AES/BSM/TLM

SITE INFORMATION

SITE NAME: HWM-NY-SUF-415 **LATITUDE (DD to 6 places):** 40.7741
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: Mastic **LONGITUDE (DD to 6 places):** -72.8161

STATE: NY **COUNTY:** Suffolk **Landowner notified (circle one):** Yes (No)

HWM INFORMATION

HWM identified with: colored flagging, (marker), stake, (disc), spray paint, other _____
Type of mark: debris line, mud line, (seed line), wash line, other _____
Mark location (circle one): Inside Outside **Approx. height above ground (ft):** 3.73
Quality of mark (circle one): Excellent (+/- 0.05 ft) (Good) (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Seed line on fence in front of #7 Shore Dr

HWM Elevation: 6.513 ft above NAVD88

RM Description: Mag nail in front of #7 House on Shore Dr.

RM #: 19 **RM Elevation:** 2.425 ft above NAVD88

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: Yes No **Camera Owner:** _____

Digital Photo Filenames: HWM-NY-SUF-415-(01 to 04).jpg

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: _____ STORM: _____ PARTY: _____

SITE MAP



Additional Notes:

Check HWM on mail box