Ocean Beach

High Water Mark Field Form

(one form per HWM)

SUF-419
Quick Lookup #

DATE: 11/3/12 STORM: Sandy PARTY: AES/TLM/BJM/CES

SITE INFORMATION

SITE NAME: HWM-NY-SUF-419 **LATITUDE (DD to 6 places):** N 40.644
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: Ocean Rd, Ocean Beach **LONGITUDE (DD to 6 places):** W 73.157

STATE: NY **COUNTY:** Suffolk **Landowner notified (circle one):** Yes (No)

HWM INFORMATION

HWM identified with: colored flagging, marker, stake, (disc), spray paint, other _____
Type of mark: debris line, (mud line), seed line, wash line, other _____
Mark location (circle one): Inside Outside **Approx. height above ground (ft):** 3.66
Quality of mark (circle one): (Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: mud line on foundation of 064 Ocean Rd on "Bonnie Dune" blue house

HWM Elevation: TBM1 + 0.356 elev HWM Elev 8.01 ft

RM Description: chiseled square on 19th piling from ocean beach town line

RM #: TBM1 **RM Elevation:** 10 (arbitrary)

Other Notes: Notify DEC, house at end of Ocean Rd off foundation, prob cess pool problem

++++ +++ ++++ ++++ ++++ ++++ ++++ ++++ ++++ ++++ 1

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** AES

Digital Photo Filenames: HWM-NY-SUF-419-(01to17).jpg

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: _____ STORM: _____ PARTY: _____

SITE MAP



Additional Notes:

_____

_____

_____

_____