Montauk

High Water Mark Field Form

(one form per HWM)

SUF-424
Quick Lookup #

DATE: 11/4/12 STORM: Sandy PARTY: AES/BYM/TLM

SITE INFORMATION

SITE NAME: HWM-NY-SUF 424 **LATITUDE (DD to 6 places):** 41.0063
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: Napeague Harbor **LONGITUDE (DD to 6 places):** -72.0350

STATE: NY **COUNTY:** Suffolk **Landowner notified (circle one):** Yes (No)

HWM INFORMATION

HWM identified with: colored flagging, marker, stake, disc, spray paint, other _____
Type of mark: debris line, mud line, seed line, wash line, other _____
Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** 1.92
Quality of mark (circle one): (Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: washline on concrete wall on southern corner of 73 Napeague Harbor Rd property marked 67' from east end of concrete

HWM Elevation: 5.200

RM Description: BM1 nail in face board on bulkhead, l.w. most nail in front of 4th post f/left end of bulkhead
RM1 corner of block wall at end of bulkhead

BM 1 6.319
RM #: 1 **RM Elevation:** 6.784

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** AES

Digital Photo Filenames: HWM-NY-SUF-424-(01 to 06).jpg

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: _____ STORM: _____ PARTY: _____

SITE MAP



Additional Notes:

check HWM 1 on shed west of wall

2 on dumpster, confirms no higher wls