East Hampton

High Water Mark Field Form

(one form per HWM)

SUF-427
Quick Lookup #

DATE: 11/4/12 STORM: Sandy PARTY: AES / BJM / TLM

SITE INFORMATION

SITE NAME: HWM-NY-SUF-427 **LATITUDE (DD to 6 places):** 41.0039
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: Three mile Harbor **LONGITUDE (DD to 6 places):** -72.1866

STATE: NY **COUNTY:** Suffolk **Landowner notified (circle one):** Yes (No)

HWM INFORMATION

HWM identified with: colored flagging, (marker), stake, disc, spray paint, other
Type of mark: debris line, mud line, seed line, (wash line), other
Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** 1.4'
Quality of mark (circle one): Excellent (+/- 0.05 ft) (Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: wash line on white cinder block wall at #16 Island Rd, 5' from eastern edge Excellent seed line on retaining wall and 3 sides of house.

HWM Elevation: 6.062

RM Description: Tempory GPS HUB set at end of street and 20p nail ~~RM1~~ RP1 (ESR) in Power Pole between house #16 and House #18, with Flaggin. GPS Elevation = 3.112 ft AB NAVD88 From Trimble R8 (Keynet)

~~RM~~ RP #: 1 **RM Elevation:** 5.357

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** AES, ADC

Digital Photo Filenames: HWM-NY-SUF-427-(01 to 13).jpg

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: _____ STORM: _____ PARTY: _____

SITE MAP



Additional Notes:

Check HWM on house transpose to 30" oak
two due west