North Haven

High Water Mark Field Form

(one form per HWM)

SUF-429
Quick Lookup #

DATE: 11/5/12 STORM: Sandy PARTY: ACS/BJM/TCM

SITE INFORMATION

SITE NAME: HWM-NY-SUF-429 **LATITUDE (DD to 6 places):** 41.0136
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: North Haven, South **LONGITUDE (DD to 6 places):** -72.3032

STATE: NY **COUNTY:** Suffolk **Landowner notified (circle one):** (Yes) No

HWM INFORMATION

HWM identified with: colored flagging, marker, stake, disc, spray paint, other_____
Type of mark: debris line, mud line, seed line, wash line, other _____
Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** 2.1
Quality of mark (circle one): Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: seed line on north side of house #6 West Harbor Dr, transposed to 5" cypress tree 22 ft NE of house corner (w/hand line/Line level)
11/6/2012 - GPS loop and shot HWM on House to verify transposed HWM 429
HWM Elevation: 6.40

RM Description: Highest point of Boulder on inside of curve of North Haven St in front of house #6. chiseled square, Painted yellow.

RM #: 1 **RM Elevation:** 7.76

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** ACS, ADL

Digital Photo Filenames: HWM-NY-SUF-429-(01 to 12).jpg

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: _____ STORM: _____ PARTY: _____

SITE MAP



Additional Notes:

Check HWM on stairs & storage container