North Haven

High Water Mark Field Form

(one form per HWM)

SUF-430
Quick Lookup #

DATE: 11/5/12 STORM: Sandy PARTY: AES/BJM/TLH

SITE INFORMATION

SITE NAME: HWM-NY-SUF-430 **LATITUDE (DD to 6 places):** 41.0371
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: North Haven, North **LONGITUDE (DD to 6 places):** -72.3197

STATE: NY **COUNTY:** Suffolk **Landowner notified (circle one):** Yes (No)

HWM INFORMATION

HWM identified with: colored flagging, marker, stake, (disc), spray paint, other _____
Type of mark: debris line, mud line, (seed line), wash line, other _____
Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** 1.9
Quality of mark (circle one): (Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Seed line on north side of pole POST 8' NW of fence in North Haven Shores Private Beach at end of North Dr
Excellent seed line, Duplex NAIL not bent down to top of head is level w/ HWM.

HWM Elevation: 6.450

RM Description: Highest point of pipe that had been cut off close to ground level in Asphalt leading to Boat Dock

RM #: 1 **RM Elevation:** 4.673

Other Notes:
High point on old steel pipe set in Concrete 1.75" Above old Asphalt road 125' from gate, inside of curve

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** ADL

Digital Photo Filenames: HWM-NY-SUF-430-(01 to 10).jpg

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/6 STORM: SANDY PARTY: ESR/DAS



Additional Notes:

_____

_____

_____

_____