North Sea

High Water Mark Field Form

(one form per HWM)

SUF-433
Quick Lookup #

DATE: 11/5/12 STORM: Sandy PARTY: AED / BJM / TCM

SITE INFORMATION

SITE NAME: HWM-NY-SUF - 433 **LATITUDE (DD to 6 places):** 40.9598
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: Rose Grove **LONGITUDE (DD to 6 places):** -72.3982

STATE: NY **COUNTY:** Suffolk **Landowner notified (circle one):** Yes (No)

HWM INFORMATION

HWM identified with: colored flagging, (marker), stake, (disc), spray paint, other _____
Type of mark: debris line, mud line, seed line, wash line, other _____
Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** _____
Quality of mark (circle one): (Excellent) (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: wash line on gate to #76 Peconic Bay Ave transposed to tree behind mailbox

HWM Elevation: 6.534

RM Description: PK NAIL SET IN ASPHALT Between Driveways to #68 AND #70 Peconic Bay Ave.

RM #: GPS001 **RM Elevation:** 3.514

Other Notes:
SHOT SEED LINE ON GATE Directly - Could not Get clear shot on Nail/DISC AND WORKING AGAINST LOSING

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** DCS, ADL

Digital Photo Filenames: HWM-NY-SUF-433-(01 to 14).jpg

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/5/12 STORM: Sandy PARTY:

SITE MAP



Additional Notes:

Check HWM on mailbox #74 (second line)