Port Jefferson

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/2/12 STORM: Sandy PARTY: ADL/RAS/ESR

SITE INFORMATION

SITE NAME: HWM-NY-SUF-509 **LATITUDE (DD to 6 places):** 40.945739
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: Port Jefferson - Barnum Ave. **LONGITUDE (DD to 6 places):** 73.071980

STATE: NY **COUNTY:** SUFFOLK **Landowner notified (circle one):** Yes (No)

HWM INFORMATION

HWM identified with: colored flagging, (marker), stake, disc, spray paint, other pencil
Type of mark: debris line, mud line, (seed line), wash line, other
Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** 1.82
Quality of mark (circle one): (Excellent) (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Seed line on outside of building located @ 232 Barnum Ave. (Pediatric Cardiology)

HWM Elevation: 8.794 ft.

RM Description: Sq. cut in lamp post.

RM #: TBM 2 **RM Elevation:** 6.888 ft.

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** ADL

Digital Photo Filenames: HWM-NY-SUF-509-(01-06).jpg

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/2/12 STORM: Sandy PARTY: ADL/RAS/ESR

SITE MAP



Additional Notes: