Northport

High Water Mark Field Form

(one form per HWM)

SUF-517
Quick Lookup #

DATE: 11/4/2012 STORM: SANDY PARTY: ADL/DAS/ESR

SITE INFORMATION

SITE NAME: HWM-NY-SUF-517 **LATITUDE (DD to 6 places):** 40.90030318
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: Northport Harbor - Seymor's Boat Yard **LONGITUDE (DD to 6 places):** 73.35302952

STATE: NY **COUNTY:** Suffolk **Landowner notified (circle one):** Yes No

HWM INFORMATION

HWM identified with: colored flagging, marker, stake, disc, spray paint, other _____
Type of mark: debris line, mud line, seed line, wash line, other observed seed line - cut in door jamb
Mark location (circle one): Inside Outside **Approx. height above ground (ft):** 3.72
Quality of mark (circle one): Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: line cut into jamb of sliding door on back side of Seymor's Boat yard. Lines correspond to good seed lines, And were cut in by operator of boat yard. (PM tide - 10/29/12)

HWM Elevation: 9.457

RM Description: Square cut on curb near entrance to pier.

RM #: TBM 2 **RM Elevation:** 5.306

Other Notes:
@ Northport Park

PHOTOGRAPH INFORMATION

Pictures Taken: Yes No **Camera Owner:** ADL

Digital Photo Filenames: HWM-NY-SUF-517-(01-09).jpg

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/4/2012 STORM: SANDY PARTY: ESR/DAS/ADL



Additional Notes:

_____

_____

_____

_____