LOCATION: HUNTINGTON NY 11743

# High Water Mark Field Form

(one form per HWM) LH#4

SUF-603
Quick Lookup #

DATE: 11/1/12 STORM: Sandy PARTY: IJF / SLR

## *SITE INFORMATION*

**SITE NAME:** HWM-NY-SUF-603 **LATITUDE (DD to 6 places):** N40.89717
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

**SITE DESCRIPTION:** Town of Huntington Gold Star Launch Service Huntington NY 11743 **LONGITUDE (DD to 6 places):** W073.43498

**STATE:** NY **COUNTY:** SUFFOLK **Landowner notified (circle one):** Yes (No)

## *HWM INFORMATION*

**HWM identified with:** colored flagging, (marker), stake, disc, spray paint, other _____
**Type of mark:** (debris line), mud line, seed line, wash line, other _____
**Mark location (circle one):** Inside (Outside) **Approx. height above ground (ft):** 0
**Quality of mark (circle one):** Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

## *ELEVATION INFORMATION*

**HWM Description:** Rack line IN HUNTINGTON NY 11743

**HWM Elevation:** 9.60 ft

**RM Description:** Survey marker, round silver disk w/ nail in ~~as~~ no parking zone, near yellow bldg, spray paint orange paint ~ 50 ft from west fence

**RM #:** ____ **RM Elevation:** _____

**Other Notes:**

## *PHOTOGRAPH INFORMATION*

**Pictures Taken:** (Yes) No **Camera Owner:** SLR

**Digital Photo Filenames:** 100-0678 – 0680 (HWM-SUF-603-01 THRU 03)

Please complete site sketch on reverse

# High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/1/12 STORM: Sandy PARTY: SLR/IJF

***SITE MAP***




**Additional Notes:**

2nd Hwm, orange tape on Fence @ end of "ramp" under "NO Dogs Allowed" sign

0.34' up from Horizonal pole in fence

N 40.89733

W 073.43506