LOCATION: CENTERPORT NY 11721

High Water Mark Field Form

(one form per HWM)

SUF-605
Quick Lookup #

DATE: 11/1/12 STORM: SANDY PARTY: SLR & JOF

SITE INFORMATION

SITE NAME: HWM-NY-SUF-605 **LATITUDE (DD to 6 places):** 40.89243
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: 100 Center Shore Rd. CENTERPORT NY 11721 **LONGITUDE (DD to 6 places):** 073.37453 less than 5 satellites

STATE: NY **COUNTY:** SUFFOLK **Landowner notified (circle one):** (Yes) No

HWM INFORMATION

HWM identified with: colored flagging, marker, stake, disc, spray paint, (other) ☑
Type of mark: debris line, mud line, seed line, wash line, other
Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** 1.42' UP FROM DOOR JAM
Quality of mark (circle one): (Excellent (+/- 0.05 ft)) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: SEED LINE ON DOOR. THIRD DOOR FROM CENTER SHORE Rd and Mill Dam Rd IN CENTERPORT NY 11721

HWM Elevation: 1.42' up from door jam (9.631 NAVD 88)

RM Description: chiseled square on south side parking lot of Grist Mill Park on Mill Dam Rd. (across street from HWM)

RM #: TBM1 **RM Elevation:** 8.250

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** SLR

Digital Photo Filenames: 100-0689-95 (HWM-NY-SUF-605-01 THRU 07)

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/1/12 STORM: SANDY PARTY: IJF & SLR

SITE MAP



Additional Notes:

2nd HWM inside 1st Door on left 1.29' up from tile floor

This site is just north of HWM #1 #2