Bellport

High Water Mark Field Form

(one form per HWM)

SUF-620
Quick Lookup #

DATE: 11/3/12 STORM: SANDY PARTY: SLR/IJF

SITE INFORMATION

SITE NAME: HWM-NY-SUF-620 **LATITUDE (DD to 6 places):** 40.75282
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: Bellport Village Marina **LONGITUDE (DD to 6 places):** 072.93438

STATE: NY **COUNTY:** SUFFOLK **Landowner notified (circle one):** Yes No

HWM INFORMATION

HWM identified with: colored flagging, marker, stake, disc, spray paint, (other) ▽ ON WALL
Type of mark: debris line, mud line, (seed line), wash line, other
Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** 1.47 ft
Quality of mark (circle one): (Excellent (+/- 0.05 ft)) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: 1st SEED LINE ON PARK WALL 1.47 ft above cement curb, Corner mark 2nd inside corner left side of door 1.80 ft above LS

HWM Elevation: 5.617 ft above NAVD 88

RM Description: Stake 4.8' from corner of building 0.17' above LS and 1.16 above top of stake.

RM #: Y373 **RM Elevation:** 3.790 ft abov NAVD 88

Other Notes:
west parking lot, cement porch wall, South of wall

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** SLR

Digital Photo Filenames: 100-0823 - 0830 HWM-NY-SUF-620-(01-08).jpg

Please complete site sketch on reverse

1.33
- .17
1.16

- 0.17 is height stake sticks out of ground
seed line 1.33 up on wall

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/3/12 STORM: SANDY PARTY: IJF & SLR

SITE MAP



Additional Notes:

3 HWMs, 3 ∇, + 1 stake