Lindenhurst

High Water Mark Field Form

(one form per HWM)

SUF-621
Quick Lookup #

DATE: 11/5/12 STORM: Sandy PARTY: IJF / MJS

SITE INFORMATION

SITE NAME: HWM-NY-SUF-621 **LATITUDE (DD to 6 places):** 40.66942
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: Moose lodge on S. Broadway Ave **LONGITUDE (DD to 6 places):** 073.36786

STATE: NY **COUNTY:** Suffolk **Landowner notified (circle one):** Yes (No)

HWM INFORMATION

HWM identified with: colored flagging, marker, stake, (disc), spray paint, other _____
Type of mark: debris line, mud line, (seed line), wash line, other _____
Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** 2.75'
Quality of mark (circle one): (Excellent (+/- 0.05 ft)) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Seed line, 2.75' up from cement pad NW side of Moose lodge, back of bldg near single brown door

HWM Elevation: 6.751 ft above NAVD 88

RM Description: Silver USGS marker, in pavement, ~ 20' west of HWM near curb

RM #: 25 **RM Elevation:** 3.555 ft Above NAVD 88

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** IJF

Digital Photo Filenames: HWM-NY-SUF-621-(01-08).jpg

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/5/12 STORM: Sandy PARTY: IJF / MJS

SITE MAP



Additional Notes:

HWM is 3.47' up from RM in pavement next to curb, used level to put in RM

2nd HWM is seed, back of bldg, 2.86' up from pavement

N 40.66932

W 073.36769