Brightwaters

High Water Mark Field Form

(one form per HWM)

SUF-624
Quick Lookup #

DATE: 11/5/12 STORM: Sandy PARTY: MJS / IJF

SITE INFORMATION

SITE NAME: HWM-NY-SUF-624 **LATITUDE (DD to 6 places):** 40.70386
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: Brightwaters **LONGITUDE (DD to 6 places):** 073.25247

STATE: NY **COUNTY:** Suffolk **Landowner notified (circle one):** Yes (No)

HWM INFORMATION

HWM identified with: colored flagging, marker, (stake), disc, spray paint, other _____
Type of mark: (debris line), mud line, seed line, wash line, other _____
Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** 3.35'
Quality of mark (circle one): Excellent (+/- 0.05 ft) (Good) (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: 3.35' up from land surface in bush, bush has a clear debris line
3.22' up from top of stake

HWM Elevation: _____ - same location as HWM-NY-SUF-406

RM Description: Stake is 0.18 feet out of ground in front of HWM

RM #: _____ **RM Elevation:** _____

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** IJF

Digital Photo Filenames: HWM-NY-SUF-624(01-07).jpg

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/5/12 STORM: Sandy PARTY: MJS / IJF

SITE MAP



Additional Notes:

2nd HWM, mark w/ USGS marker on tree N40.70394, W073.25239
1.92' up on tree, nail marks spot