ay Shore

High Water Mark Field Form

(one form per HWM)

SUF-625
Quick Lookup #

DATE: 11/5/12 STORM: Sandy PARTY: MJS/IJF

SITE INFORMATION

SITE NAME: HWM-NY-SUF-625 **LATITUDE (DD to 6 places):** 40.71270
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: 21 Bayview Dr **LONGITUDE (DD to 6 places):** 073.24317

STATE: NY **COUNTY:** Suffolk **Landowner notified (circle one):** (Yes) No

HWM INFORMATION

HWM identified with: colored flagging, (marker), stake, disc, spray paint, other ▽
Type of mark: debris line, mud line, (seed line), wash line, other
Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** 3.15'
Quality of mark (circle one): (Excellent) (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: seed line, in back of house, on cement shed that has oil burner in it
3.15' up from land surface NE side of shed back of house

HWM Elevation: - Same location as HWM-NY-SUF-407

RM Description: ▽ back of house, on cement shed

RM #: **RM Elevation:**

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** IJF

Digital Photo Filenames: HWM-NY-SUF-625-(01-12).jpg

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/5/12 STORM: Sandy PARTY: MJS/ISF

SITE MAP



Additional Notes:

2nd HWM - SE corner of house ▽, 3.45' up from land surface

N 40.71260

W 073.24300