Great River

# High Water Mark Field Form

(one form per HWM)

SUF-627
Quick Lookup #

DATE: 11/5/12 STORM: Sandy PARTY: JJF/MJS

## SITE INFORMATION

**SITE NAME:** HWM-NY-SUF-627 **LATITUDE (DD to 6 places):** 40.71995
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

**SITE DESCRIPTION:** Timber Pt County Marina **LONGITUDE (DD to 6 places):** 073.14118

**STATE:** NY **COUNTY:** Suffolk **Landowner notified (circle one):** Yes (No)

## HWM INFORMATION

**HWM identified with:** colored flagging, marker, (stake) disc, spray paint, other _____
**Type of mark:** (debris line) mud line, seed line, wash line, other _____
**Mark location (circle one):** Inside (Outside) **Approx. height above ground (ft):** 0
**Quality of mark (circle one):** Excellent (+/- 0.05 ft) (Good) (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

## ELEVATION INFORMATION

**HWM Description:** rack line located behind marina, close to green on golf course

**HWM Elevation:** 5.538 ft above NAVD88

**RM Description:** stake in ground, sticking up 0.25' above land surface

**RM #:** _____ **RM Elevation:** _____

**Other Notes:**

## PHOTOGRAPH INFORMATION

**Pictures Taken:** (Yes) No **Camera Owner:** JJF

**Digital Photo Filenames:** HWM-NY-SUF-627-(01-09).jpg

Please complete site sketch on reverse

# High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/5/12 STORM: Sandy PARTY: MJS/IJF

***SITE MAP***




**Additional Notes:**

2nd HWM on Bathroom Bldg, in back NW side
N 40.72015, W 073.14092
3.25' up from land surface