Oakdale

High Water Mark Field Form

(one form per HWM)

SUF-628
Quick Lookup #

DATE: 11/5/12 STORM: Sandy PARTY: MJS / IJF

SITE INFORMATION

SITE NAME: HWM-NY-SUF-628 **LATITUDE (DD to 6 places):** N 40.72770
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: Consuelo Place **LONGITUDE (DD to 6 places):** W073.14200

STATE: NY **COUNTY:** Suffolk **Landowner notified (circle one):** (Yes) No

HWM INFORMATION

HWM identified with: colored flagging, (marker), stake, disc, spray paint, other ▽
Type of mark: debris line, mud line, (seed line), wash line, other
Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** 2.1'
Quality of mark (circle one): (Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Seed line located 2.1' above land surface on white PVC fence

HWM Elevation: 5.801 ft Above NAVD88

RM Description: ▽ drawn on white Fence, 1.54' cyclone fence

RM #: 9 **RM Elevation:** 2.933 ft. Above NAVD88

Other Notes: Mag nail in front of House #15 Consuela Place Oakdale.

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** IJF

Digital Photo Filenames: HWM-NY-SUF-628-(01-06).jpg

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/5/12 STORM: Sandy PARTY: MJS/JSF

SITE MAP



Additional Notes:

2nd HWM 1.54' N40.72766 W073.14204