Blue Point

High Water Mark Field Form

(one form per HWM)

SUF-631
Quick Lookup #

DATE: 11/5/12 STORM: Sandy PARTY: IJF / MJS

SITE INFORMATION

SITE NAME: HWM-NY-SUF-631 **LATITUDE (DD to 6 places):** 40.73158
(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: Entrance to Sayville Yacht Club **LONGITUDE (DD to 6 places):** 073.03650

STATE: NY **COUNTY:** Suffolk **Landowner notified (circle one):** Yes (No)

HWM INFORMATION

HWM identified with: colored flagging, (marker), stake, disc, spray paint, other ▽
Type of mark: debris line, mud line, (seed line), wash line, other
Mark location (circle one): Inside (Outside) **Approx. height above ground (ft):** 3.13'
Quality of mark (circle one): (Excellent) (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: seed line on wood fence + seed line on post of Sayville Yacht club sign

HWM Elevation: 5.572 ft above NAVD 88

RM Description: ▽ on Fence, southside of driveway

RM #: 12 **RM Elevation:** 4.922 ft above NAVD 88

Other Notes:

PHOTOGRAPH INFORMATION

Pictures Taken: (Yes) No **Camera Owner:** MJS smart phone

Digital Photo Filenames:

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/5/12 STORM: Sandy PARTY: MJS / IJF

SITE MAP



Additional Notes:

2nd HWM is 2.82' up from land surface on right post of sign N40.73157 W073.03642