Brookhaven

High Water Mark Field Form

(one form per HWM)

SUF-635
Quick Lookup #

DATE: 11/6/2012 STORM: SANDY PARTY: IF & GEK

SITE INFORMATION

SITE NAME: HWM-NY-SUF-635 **LATITUDE (DD to 6 places):** 40.77322

(Site Name Format: HWM-SS-COU-###, where SS = state, COU = county, ### = site number)

SITE DESCRIPTION: ON THE (whole side of house) 3 Newey Lane Brookhaven **LONGITUDE (DD to 6 places):** 072.89910

STATE: NY **COUNTY:** SUFFOLK **Landowner notified (circle one):** Yes No

HWM INFORMATION

HWM identified with: colored flagging, marker, stake, disc, spray paint, other_____

Type of mark: debris line, mud line, seed line, wash line, other _____

Mark location (circle one): Inside Outside **Approx. height above ground (ft):** 1.38 from ground

Quality of mark (circle one): Excellent (+/- 0.05 ft) Good (+/- 0.10 ft) Fair (+/- 0.25 ft) Poor (>0.25 ft)

ELEVATION INFORMATION

HWM Description: Seed line present on side house of property 3 Newey lane 1.38' from ground + 1.17' from top of stake to HWM

HWM Elevation: 5.229 ft Above NAVD 88

RM Description: orange stake in ground not flush. 0.26 ft from ground and top of stake to HWM 1.17 ft.

RM #: 15 **RM Elevation:** 4.779 NAVD88 tape up to HWM = 0.45 ft from RM 15 (stake @ grade)

PHOTOGRAPH INFORMATION

Pictures Taken: Yes No **Camera Owner:** IF

Digital Photo Filenames: HWM-NY-SUF-635-(01-06).jpg

Please complete site sketch on reverse

High Water Mark Field Form

(one form per HWM)

Quick Lookup #

DATE: 11/6/2012 STORM: SANDY PARTY: IF & GEK

SITE MAP



Additional Notes: